IN THE UNITED STATES PATENT AND TRADEMARK OFFICE

In re Patent No.: 7.327.400

Inventor: Robert Y. GREENBERG

Issued: February 5, 2008

 Ser. No.:
 09/888,271
 Filed:
 June 21, 2001

 Group Art Unit:
 2622
 Examiner:
 Trang U. TRAN

For: AUTOMATIC PHASE AND FREQUENCY ADJUSTMENT CIRCUIT

AND METHOD

REOUEST FOR CERTIFICATE OF CORRECTION

Commissioner for Patents P.O. Box 1450 Alexandria, VA 22313-1450

Upon comparison of the above-identified original Letters Patent with applicant's copy of the application, the following errors, <u>made by the USPTO</u>, in the original Letters Patent has been noted:

Column 3, line 25, the words "detects 11" should read -- detects --;

Column 4, line 41, the word "phi" should read -- ph1 --;

Column 6, line 19, the words "11 with" should read -- with --;

Column 6, line 25, the words "ph6 hit en" should read -- ph6 hit en --;

Column 6, line 28, the words "ph6 hit en" should read -- ph6 hit en --.

Applicant respectfully requests that a Certificate of Correction calling attention to the above error be issued pursuant to Rule 322 of the Patent Office and Title 35, United States Code, Section 254

> Respectfully submitted, MARGER JOHNSON & McCOLLOM, P.C.

Julie L. Reed Reg. No. 35,349

MARGER JOHNSON & McCOLLOM, P.C. 210 SW Morrison Street, Suite 400 Portland, OR 97204 503-222-3613 U.S. Patent and Trademark Office (U.S. DPARTMENT OF COMMENCE)

U.S. Patent and Trademark Office (U.S. DPARTMENT OF COMMENCE)

Under the Paperwork Reduction Act of 1995, no persons are required to respond to a collection of information unless it displays a valid OMB control number.

(Asso Form PTO-1090)

UNITED STATES PATENT AND TRADEMARK OFFICE CERTIFICATE OF CORRECTION

Page	1	of	- 1

PATENT NO. : 7,327,400 APPLICATION NO.: 09/888,271

ISSUE DATE : February 5, 2008

INVENTOR(S) : Robert Y. GREENBERG

It is certified that an error appears or errors appear in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

Column 3, line 25, the words "detects 11" should read — detects —; Column 4, line 41, the word "phi" should read — ph1 —; Column 6, line 19, the words "11 with" should read — with —; Column 6, line 25, the words "ph6 hit en" should read — ph6 hit en —; Column 6, line 28, the words "ph6 hit en", should read — ph6 hit en —;

MAILING ADDRESS OF SENDER (Please do not use customer number below):

MARGER JOHNSON & McCOLLOM, P.C. 210 SW Morrison Street, Suite 400 Portland, OR, 97204

This collection of information is required by 37 CPR 1.322, 1.323, and 1.324. The information is required to obtain or retain a beginning formation in the first of the control of the con